



BUENA VISTA RANCHERIA
BAND OF ME-WUK INDIANS
1418 20TH STREET
SACRAMENTO, CA 95811
916-491-0011



Erosion caused by stormwater runoff from storm in January 2023

Erosion issues Buena Vista Peaks tributaries to the western stream



Eroding tributary from BV Peak property that feeds into the western stream during storm events. This is a candidate for stormwater control bioswale project. Photographed January 2023



This is a swale on the BVR Peaks Property that flows into the western stream. This is a stormwater control project candidate that could be restored to improve functional stormwater capacity and incorporate native vegetation.